TECH▴TIP

Smartlink units- no mode displayed on the PCON

Tools Needed:

CAT5 Cable
PC or Laptop Computer

Model:

All Models with Smart Link Control System Rev T software- Slab Scissors, GR/GRC/QS, 69BE/DC, GS1330M updated in the field

Genie
A TEREX BRAND

TECH▴PRO™

SERVICE AND TECHNICAL TRAINING

TECH▴TIP

Tech Tips Safety Rules

Danger

Failure to obey the instructions and safety rules in the appropriate Operator's Manual and Service Manual for your machine will result in death or serious injury. Many of the hazards identified in the operator's manual are also safety hazards when maintenance and repair procedures are performed.

Do Not Perform Maintenance Unless:
- ➢ You are trained and qualified to perform maintenance on this machine.
- ➢ You read, understand and obey:
  - o manufacturer's instructions and safety rules
  - o employer's safety rules and worksite regulations
  - o applicable governmental regulations
- ➢ You have the appropriate tools, lifting equipment and a suitable workshop.

The information contained in this tech tip is a supplement to the service manual. Consult the appropriate service manual of your machine for safety rules and hazards.

Step 1

On Revision T, with the telematics option turned on, if function is selected at the right time during start-up, the selected mode of operation will not appear on the PCON screen. The screen will instead be blank.

Step 2

Update software to Rev "W" or higher using the process the the applicable Service Manual "Loading or Updating Machine Software".